## Ride-On-Tractor

Date of Inspection: 3/18/2025	Hours: 598		
Completed by:	S/N#:		
Equipment Year / Make / Model: 2006 / Ditch Witch / RT115			

	Poor	Fair	Good	v. Good	Exc.
Description	1	2	3	4	5
General Appearance:					
CE Mark Present (check SN# plate) (Y/N)			х		
Paint Condition		х			
Sheet Metal / Fiberglass			х		
Steps / Ladders			х		
Safety Rails / Hand Rails			х		
				1 1	

	Poor	Fair	Good	v. Good	Exc.
Description	1	2	3	4	5
Hydraulics					
Hydraulic Pumps		х			
Hydraulic Motors		х			
Valves		x			
Hoses		х			
Cylinders		х			
Cylinders pins / bushings		x			

Control Station:		
Seats / Armrests	х	
Seat Belts	х	
Hydraulic Controls	x	
Steering Controls	х	
Drivetrain Controls	x	
Oil Pressure	х	
Exterior Lights Operations? (Y/N)	x	
Engine Warning Lights	х	
Gauges	х	
Hour Meter / Odometer	х	
Limited Function Check Results: (joysticks operations, gauges readable, hour meter functional)	х	

Trencher Attachment		
Model/SN		
Chain/Sprocket Condition	x	
Pockets/Teeth/Base Plate Condition	x	
Augers/Bearings	x	
Top/Bttom Wear Plates	x	
Sliding Offset Cylinder/Slides if Applicable	x	
End Idler Condition	x	
Crumber/Cylinder/Lock	x	
Boom Lift Cylinders/Pins	x	
Hose Condition	x	
Attachment Pivot Rings	x	

	-		_	T
Engine:				
Make / Model John Deere				
Fuel Type Diesel				
Emmission Control Label Present? (Y/N)	у			
Last service dates 1/15/2025				
Transmission		х		
Limited Function Check Results: (engine start/stop, visual blowby, throttle, emergency stop, leaks)		x		
Backhoe Attachment (If Apllicable)				
Model/SN				
Cylinders/Hose Condition		х		
Bucket Condition		х		
Outriggers		х		
Plow Attachment (If Applicable)				
Model/SN				
Blade Condition/ Blade Dimensions		х		
Shaker Box		х		
Cylinders/Hoses Condition		х		

+	_	

lotes:	Total cost of repairs:			